

Date : 04/07/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 04/07/2024 8:00
Onsite Hours : 06:00

ASEC Report ID : 65927
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 04/07/2024 14:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- The placement and compaction of backfilling GAB between storm water line MH A-1 and MH A-1 and backfilling with M10 sand for the existing storm water line continued this day.
- At the time of arrival, our representative observed that work was in progress with 1-foot lifts being placed and compacted using sheep's-foot and trench compaction equipment.
- Density test results indicate that the compacted materials met the project requirement of 95% of the maximum dry density obtained by the (modified proctor).
- ABC performed saw cut for under drainage at phase 7A.
- Kelly Construction was performing backfilling for storm water RCP between MH A-1 and MHA-2.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/07/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 04/07/2024 8:00
Onsite Hours : 06:00

ASEC Report ID : 65927
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 04/07/2024 14:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.