

Date : 05/23/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 05/23/2023 9:00
Onsite Hours : 08:00

ASEC Report ID : 59481
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : cloudy
Departure Time : 05/23/2023 17:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The placement and compaction of backfill soils for Lots #415, 416 and 417 continued this day.



At the time of arrival, our representative observed that work was in progress with lifts being placed to about 20 feet below finished grade and compacted using a 810 compactor.

The density test results are on hold until I receive the proctor from the lab, however, in-place moisture contents were found to be high.



Date : 05/23/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 05/23/2023 9:00
Onsite Hours : 08:00

ASEC Report ID : 59481
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : cloudy
Departure Time : 05/23/2023 17:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.