

Date : 02/24/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/24/2023
Onsite Hours :

ASEC Report ID : 57297
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : cloudy
Departure Time : 02/24/2023
ASEC Technician Name : Vidal Dias

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities.

During the visit, the following observations were made:

1. The Terrafabric was placed in the basement's upper half on the ramp's east slope.
2. The fabric was placed in accordance with the specifications on drawing E720667.

Photo documentation and photo locations are included below:



Terrafabric in the basement's upper half on the ramp's east slope



Terrafabric in the basement's upper half on the ramp's east slope



Terrafabric in the basement's upper half on the ramp's east slope

Date : 02/24/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/24/2023
Onsite Hours :

ASEC Report ID : 57297
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : cloudy
Departure Time : 02/24/2023
ASEC Technician Name : Vidal Dias



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.