

Date : 05/02/2024  
Project No : 2024C112  
Client Company : SR Homes  
Arrival Time : 05/02/2024 8:30  
Onsite Hours : 08:30

ASEC Report ID : 66330  
Name of the Project : Sterlington  
Project Location : Canton  
Weather : sunny  
Departure Time : 05/02/2024 17:00  
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The undersigned arrived onsite to observe CMU block placement for retaining wall #1 and visually inspect the footings.

- 1: The footing was observed by our ASEC representative, Russell Hendrix. It was recommended to remove approximately 6 inches of soil and replace with #57 stone to work above the water intrusion.
- 2: Our representative noted the backfill behind the block in the cells was #57 stone.
- 3: The soil backfill was placed in 12-inch compacted lifts.
- 4: No. 57 stone was utilized 1 foot behind the block and within the cells.



Date : 05/02/2024  
Project No : 2024C112  
Client Company : SR Homes  
Arrival Time : 05/02/2024 8:30  
Onsite Hours : 08:30

ASEC Report ID : 66330  
Name of the Project : Sterlington  
Project Location : Canton  
Weather : sunny  
Departure Time : 05/02/2024 17:00  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.