

Date : 12/11/2025
Project No : 2025C260
Client Company : Artisan
Arrival Time : 12/11/2025 11:30
Onsite Hours : 04:00

ASEC Report ID : 88468
Name of the Project : NW (PHASE 2) Parkway Extension
Project Location : Dallas
Weather : Sunny
Departure Time : 12/11/2025 15:30
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our representative was on site to observe the grading contractor continue placing rock fill for the slope embankment in compacted lifts using a dozer to spread and a sheep-foot vibratory roller for compacting. The fill was placed in accordance with recommendations and appeared suitably compacted as per job specifications.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Undercutting rock fill from Nature Walk Parkway near
sanitary sewer manhole #9



Date : 12/11/2025
Project No : 2025C260
Client Company : Artisan
Arrival Time : 12/11/2025 11:30
Onsite Hours : 04:00

ASEC Report ID : 88468
Name of the Project : NW (PHASE 2) Parkway Extension
Project Location : Dallas
Weather : Sunny
Departure Time : 12/11/2025 15:30
ASEC Technician Name : Clyde Smith



Fill placement at slope embankment



Wet conditions at haul road to slope embankment



Fill placement at slope embankment

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.