

Date : 11/12/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 10/15/2021 07:00
Onsite Hours : 02:00

ASEC Report ID : 34343
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : sunny
Departure Time : 10/15/2021 09:00
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today on Lot #25 at Winslow @ Brookstone:

A wall inspection was conducted for the purpose of concrete placement. The wall footing appeared suitable for concrete placement and reinforcing steel placed as per specifications for size, spacing and quantity. Please find the attached photos.

DCP LOCATION:

Lot #,
North/South/Center
etc

Depth (feet)	Set 2"	N 1.75"	Description
1		5	Fill - Brown, Silty fine Sand
2		9	Fill - Red, Silty fine Sand
3		11	Fill - Red, Silty fine Sand
4		8	Fill - Red, Silty fine Sand
5		11	Fill - Red, Silty fine Sand
6		12	Red Brown Silty Fine Sand, Residual
7		14	Red Brown Silty Fine Sand, Residual
8			
9			
10			

DCP LOCATION:

Lot #,
North/South/Center
etc

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.