

Date : 11/15/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 11/15/2021 12:00
Onsite Hours : 05:00

ASEC Report ID : 34542
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 11/15/2021 17:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- Placing storm drain in area between B1 and B1.1.
- Continuing to move rocks into excavated pits around perimeter of the site.
- Forming fill slopes from excavated soil unsuitable for structural fill.
- Rock breaking on site is continued.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.