

Date : 12/06/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 12/06/2021 08:45
Onsite Hours : 01:00

ASEC Report ID : 34735
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Cloudy / drizzle
Departure Time : 12/06/2021 09:45
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

Upon arrival it was determined that no lifts or other soil work was being completed except for preparing for additional rain. A meeting was held with the on site foreman, Baron, who stated that berms were being constructed in anticipation for rain. These Berms were intended to redirect the flow of water away from areas that would have additional lifts completed.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.