

Date : 02/24/2022
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 02/10/2022
Onsite Hours :

ASEC Report ID : 53180
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : 61 sunny
Departure Time : 02/10/2022
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

A footing inspection was requested for Lot #34 in Winslow @ Brookstone. Upon arrival all rebar was found to meet job specifications for size, spacing, and quantity. Dynamic Cone Penetrometer (DCP) testing found the footing to be suitable for a soil bearing pressure of 2000 psf. Please see the following table below for results.

DCP TEST DATA SHEET

Project Name: Winslow at Brookstone
Project Number: 2020c007
Project Location: Subdivision, lot 34
Date: 02/10/22
Technician: Russ Hendrix

DCP LOCATION:
Lot #, Footing, East,
North/South/Center etc facing road
DCP LOCATION:
Lot #,
North/South/Center etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		9	Red fine sandy silt	1			
2		14	Red fine sandy silt	2			
3		9	Gray silty fine sand	3			
4		9	Gray silty fine sand	4			
5				5			
6				6			
7				7			

Date : 02/24/2022
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 02/10/2022
Onsite Hours :

ASEC Report ID : 53180
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : 61 sunny
Departure Time : 02/10/2022
ASEC Technician Name : Russell Hendrix

8	8
9	9
10	10

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1				1			
2				2			
3				3			
4				4			
5				5			
6				6			
7				7			
8				8			
9				9			
10				10			

NOTES:
Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.