

Date : 04/02/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 04/02/2021 09:00
Onsite Hours : 01:00

ASEC Report ID : 6987
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Overcast
Departure Time : 04/02/2021 10:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today

A rebar and footing inspection was scheduled for the subject property Lot 8 and 9

- The following suggestions are made for corrective action:
 - Lot 8 Right front corner of property missing bar ties on rebar.
 - Lot 8 WWR along back right side of property requires trimming.
 - Lot 9 Front left corner of property rebar is bent so that placement is outside the acceptable area of the footing.
- If the suggested corrections are made, then rebar placement will be acceptable and within plan specifications



Lot 8 Missing Rebar Ties



Lot 8 WWR needs trimming

Date : 04/02/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 04/02/2021 09:00
Onsite Hours : 01:00

ASEC Report ID : 6987
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Overcast
Departure Time : 04/02/2021 10:00
ASEC Technician Name : Dave Bek



Lot 9 Rebar not aligned with Footing



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla

GA P.E. 036021

Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.