

Date : 08/20/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 08/20/2021 16:00
Onsite Hours : 02:00

ASEC Report ID : 33665
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 08/20/2021 18:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- drilling continued on site to blast rock and place it in the deep layers of fill.
- Blasted rock is being processed into smaller sizes acceptable for use in deeper boulder fill layers.
- Layers of rock being placed in the area of approximately lots 338 through 346.
- Soil is being mined from cut areas to cover rocks for blasting and then later be used for structural fill on site.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.