

Date : 09/08/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 09/08/2021 08:30
Onsite Hours : 01:30

ASEC Report ID : 33870
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 09/08/2021 10:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- Erosion control work is being done due to rain over the previous days.
- Drilling and preparation for blasting continues on site.
- Rock breaking continued to make rocks suitable sizes for fill lifts.



Rock Breaking on site.



Turning up soil to dry it for future filling.



Date : 09/08/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 09/08/2021 08:30
Onsite Hours : 01:30

ASEC Report ID : 33870
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 09/08/2021 10:00
ASEC Technician Name : Christopher Burrow II



Precision blasting preparing for rock blasting.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.