

Date : 09/01/2026
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 09/01/2026 13:00
Onsite Hours : 02:30

ASEC Report ID : 97373
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : sunny
Departure Time : 09/01/2026 15:30
ASEC Technician Name : Samara Simha Reddy Kandi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

DCP testing was performed at Lots 75-26 and 12-18.

Lot 75-26

DCP Test 1 - Light red sandy silt

1 ft - 11 blows
2 ft - 8 blows Light brown silty sand
3 ft - 7 blows
4 ft - 6 blows

DCP Test 2 - Light red silty sand

1 ft - 10 blows
2 ft - 9 blows
3 ft - 8 blows
4 ft - 8 blows

Lot 12-18

DCP Test 1 - Red silty clayey sand

1 ft - 12 blows
2 ft - 10 blows
3 ft - 10 blows
4 ft - 9 blows

DCP Test 2 - Red silty clayey sand

1 ft - 10 blows
2 ft - 9 blows
3 ft - 8 blows
4 ft - 8 blows

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you

Date : 09/01/2026
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 09/01/2026 13:00
Onsite Hours : 02:30

ASEC Report ID : 97373
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : sunny
Departure Time : 09/01/2026 15:30
ASEC Technician Name : Samara Simha Reddy Kandi



Date : 09/01/2026
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 09/01/2026 13:00
Onsite Hours : 02:30

ASEC Report ID : 97373
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : sunny
Departure Time : 09/01/2026 15:30
ASEC Technician Name : Samara Simha Reddy Kandi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.