Concrete Test Report

Date : 10/08/2026
Project No : 2025C214
Client Company : Artisan
Arrival Time : 10/08/2026 06:30
Onsite Hours : 04:00

ASEC Report ID : 98029
Name of the Project : NW Unit 4 BRIDGE (Materials Testing)
Project Location : Dallas
Weather : Sunny
Departure Time : 10/08/2026 10:30
ASEC Technician Name : Clyde Smith

Location(S):

Testing: 1 Set of concrete specimens (6 per set) were cast during the cast-in-place concrete pour at the above referenced location, in accordance with ASTM C31. The specimen will remain on site for the initial 24-48 hrs curing.

Compliance: ☒Field placement of concrete appeared to be in general accordance with the project specifications (i.e., slump, temperature, etc) (refer to remarks below)
☐Deviations and/or noncompliances were noted during the field placement (refer to remarks below)

Specimen Pick Up: 1 Sets of concrete specimens/ 6 specimen per set were picked up & transported to AS Engineering and Consulting LLC (ASEC) for curing and testing in accordance with ASTM C39, C670/1231

Field Curing: Specimen were stored for the initial 24 hours
☒ Near the poured structure
☐ In an insulated curing box
☐ Other

Remarks: Location: West side of bridge abutment approach slab poured a 5000-psi mix requiring 4000 psi mix. Slump 3.75, temperature air 62 degrees, mix 70 degrees. Break 1 @ 5 days, 1 @ 7 days, 3 @ 28 days and 1 reserve

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.