Concrete Test Report

ASEC Report ID : 70461
Name of the Project : Protovision PH II
Project Location : Lithia Springs
Weather :
Departure Time : 09/23/2024 07:00
ASEC Technician Name : Solomon Cherie

Date : 09/23/2024
Project No : 2024C189
Client Company : WSP
Arrival Time : 09/23/2024 01:45
Onsite Hours : 05:15

Location(S):

Testing: 5 Set of concrete specimens (5 Cylinders per set) were cast during the cast-in-place concrete pour at the above referenced location, in accordance with ASTM C31. The cylinders will remain on site for the initial 24-48 hrs curing.

Compliance: ☒Field placement of concrete appeared to be in general accordance with the project specifications (i.e., slump, temperature, etc) (refer to remarks below)
☐Deviations and/or noncompliances were noted during the field placement (refer to remarks below)

Cylinders Pick Up: 5 Sets of concrete cylinders/ 5 cylinders per set were picked up & transported to AS Engineering and Consulting LLC (ASEC) for curing and testing in accordance with ASTM C39, C670/1231

Field Curing: Cylinders were stored for the initial 24 hours
☒ Near the poured structure
☐ In an insulated curing box
☐ Other

Remarks: There was 250 yards of concrete placed, and sampling was performed every 50 cubic yards placed (5 sets).

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.