

Date : 06/02/2026
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 06/02/2026 21:30
Onsite Hours : 07:30

ASEC Report ID : 95029
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAIA, Atlanta, GA
Weather : clear
Departure Time : 06/03/2026 05:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (CWM) and for the observation/testing of the placement of fill/backfill. The contractors spread approximately 2 inches of topsoil across section 2 that was milled on the previous day. This area was walked in with equipment and will be seeded on Thursday evening. The contractors milled approximately 2 inches of soil off of section 4 and replaced with approximately 2 inches of topsoil. This area was walked in with equipment and will be seeded on Thursday evening.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 06/02/2026
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 06/02/2026 21:30
Onsite Hours : 07:30

ASEC Report ID : 95029
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAI, Atlanta, GA
Weather : clear
Departure Time : 06/03/2026 05:00
ASEC Technician Name : Sean Willett



Date : 06/02/2026
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 06/02/2026 21:30
Onsite Hours : 07:30

ASEC Report ID : 95029
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : clear
Departure Time : 06/03/2026 05:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.