

Date : 03/09/2026
Project No : 2026C103
Client Company : Artisan
Arrival Time : 03/09/2026 08:00
Onsite Hours : 9:00

ASEC Report ID : 91136
Name of the Project : NW PH 2, UNIT 4
Project Location : Dallas
Weather : sunny
Departure Time : 03/09/2026 17:00
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site to observe the pipe contractor continue installing 8" ductile iron sanitary sewer line between manhole structures #7 and 8. The writer observed backfilling at deep elevations which was placed and compacted in suitable lifts. The contractor had installed sanitary sewer line from halfway between manholes #4 and #5 and from #5 thru #7 on 3/7/26 without the writer present on site.

The grading contractor continued placing rock fill for building Lots #33 through 36 that was observed by the writer at elevation 902. The observed rock fill placement was suitable as per job specifications.


The blast contractor (Advance) made a blast shot today at Lots #45 and 46. The blast drill log is attached.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 03/09/2026
Project No : 2026C103
Client Company : Artisan
Arrival Time : 03/09/2026 08:00
Onsite Hours : 9:00

ASEC Report ID : 91136
Name of the Project : NW PH 2, UNIT 4
Project Location : Dallas
Weather : sunny
Departure Time : 03/09/2026 17:00
ASEC Technician Name : Clyde Smith



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.