

Date : 02/22/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 02/22/2021 07:00
Onsite Hours : 03:00

ASEC Report ID : 1724
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Rainy / Overcast
Departure Time : 02/22/2021 10:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

- A rebar and footing inspection was scheduled for the subject property 6172 Collins Rd, Acworth GA 30101 (Lot 5) but was unable to be performed due to there being no rebar or footings in place to be inspected at this time.
- Contacted Site Supervisor and made them aware of site conditions and was told that the inspection would be re-scheduled on a later date.



No Rebar/ No Footings



No Rebar/ No Footings



No Rebar/ No Footings

Date : 02/22/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 02/22/2021 07:00
Onsite Hours : 03:00

ASEC Report ID : 1724
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Rainy / Overcast
Departure Time : 02/22/2021 10:00
ASEC Technician Name : Dave Bek



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla

**GA P.E. 036021
Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.