

Date : 12/21/2021
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 12/06/2021 13:30
Onsite Hours : 01:00

ASEC Report ID : 52811
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : cloudy
Departure Time : 12/06/2021 14:30
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

A slab subgrade inspection request was made for Lot #7 in the "Pinnacle" section of the development. All rebar was installed to IBC requirements for size, spacing and quantity. The footing was probed and a DCP was completed and deemed suitable for concrete placement. Please see the attached data table.

DCP TEST DATA SHEET

Project Name: Suncity **Date:** 12/06/21
Project Number: 2021c060 **Technician:** Russ Hendrix
Project Location: Griffin

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		12	Red silty fine sand	1			
2		13	Red silty fine sand	2			
3		14	Red silty fine sand	3			
4		14	Red silty fine sand	4			
5				5			
6				6			
7				7			
8				8			

Date : 12/21/2021
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 12/06/2021 13:30
Onsite Hours : 01:00

ASEC Report ID : 52811
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : cloudy
Departure Time : 12/06/2021 14:30
ASEC Technician Name : Russell Hendrix

9

9

10

10

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			

NOTES:


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.