

Date : 01/20/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/12/2022 09:00
Onsite Hours : 02:00

ASEC Report ID : 52948
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 27, cold
Departure Time : 01/12/2022 11:
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

Upon arrival it was noted that all forms were completed, and rebar was correctly placed for sizing, spacing, and quantity. A DCP test was conducted on the footing facing the road frontage. Please see the attached table.

DCP TEST DATA SHEET

Project Name: Suncity **Date:** 01/20/22
Project Number: 2021c060 **Technician:** Russell Hendrix
Project Location: Griffin, GA

DCP LOCATION: Lot 74 expedition,
Lot #, Northeast at
North/South/Center etc roadfront
DCP LOCATION: Lot #,
North/South/Center etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		15	Red fine sandy silt	1			
2		15	Brown fine sandy silt	2			
3		14	brown fine sandy silt	3			
4		14	brown fine sandy silt	4			
5				5			
6				6			
7				7			
8				8			

Date : 01/20/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/12/2022 09:00
Onsite Hours : 02:00

ASEC Report ID : 52948
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 27, cold
Departure Time : 01/12/2022 11:
ASEC Technician Name : Russell Hendrix

9

9

10

10

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			

NOTES:


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.