

Date : 09/02/2021
Project No : 2021C073
Client Company : DR Horton West
Arrival Time : 09/02/2021 07:30
Onsite Hours : 02:00

ASEC Report ID : 33815
Name of the Project : Tributary C2A
Project Location : Riverside Parkway, City of Douglasville, GA
Weather : Partly cloudy
Departure Time : 09/02/2021 09:30
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities.

The following are observations that were made at this time:

- Excavations made from the mining of structural fill was filled with unsuitable material. The excavation measured approximately 46'x87'x30'.
- The contractor started installing sewer laterals at lots 430 through 439.
- Some top soils was removed in the mining but the decision was made to not pursue this further.


Top soil encountered while trenching for sewer
laterals


Top soil encountered while trenching for sewer
laterals



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.