

Date : 03/29/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 03/29/2021 09:00
Onsite Hours : 03:00

ASEC Report ID : 5938
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Overcast
Departure Time : 03/29/2021 12:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today

A slab and footing inspection was scheduled for lot 6, 7 and 8. Due to heavy rainfall the previous day both lot 6 and Lot 7 were heavily saturated, and would require “de-mucking” and re-cutting of the footings. The Rebar was in place, but inspection would need to be re-scheduled.

Two DCP density tests were performed on both lots to assess compaction. The DCP density test report for this day list the test results for the work performed on this day. Based on the density test results, and random probing of the footings, the compaction was found to be acceptable and within plan specifications.

Lot 8 was not ready for inspection. No rebar or footings were in place.



Lot 6



Lot 6 Footing (Heavy saturation) requires “de-mucking”

Date : 03/29/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 03/29/2021 09:00
Onsite Hours : 03:00

ASEC Report ID : 5938
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Overcast
Departure Time : 03/29/2021 12:00
ASEC Technician Name : Dave Bek



Lot 7

Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla

GA P.E. 036021

Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.