

Date : 11/16/2023
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 11/16/2023 8:00
Onsite Hours : 05:00

ASEC Report ID : 63082
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 11/16/2023 13:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

The installation of the 30 inches of water line was observed between STA 7028+00 to 7030+00 prior to backfill placement.



Kenneth Mosman

Kenneth Mosman

Date : 11/16/2023
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 11/16/2023 8:00
Onsite Hours : 05:00

ASEC Report ID : 63082
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 11/16/2023 13:00
ASEC Technician Name : Aminullah Azimi

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.