

Date : 03/22/2024
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 03/22/2024 15:00
Onsite Hours : 04:00

ASEC Report ID : 65556
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 03/22/2024 19:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Amin Azimi visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made during our evaluation:

Performed DCP tests for the end around for bent 15 and bent 19.

A hand auger and DCP test was performed to determine the properties of the soil.

Dynamic Cone Penetrometer (ASTM STP-399): results are below. Could not perform a deeper test due to encountering compacted graded aggregate base.

DCP1

DCP2

Depth (Feet)	Blows per 3/4" Increment	Depth (Feet)	Blows per 3/4" Increment
1	35	1	34



Date : 03/22/2024
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 03/22/2024 15:00
Onsite Hours : 04:00

ASEC Report ID : 65556
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 03/22/2024 19:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.