


Date : 05/07/2024
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 05/07/2024 7:30
Onsite Hours : 9:00

ASEC Report ID : 66437
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 05/07/2024 16:30
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.


- The placement and compaction of M10 fill and GAB was continued at bend 30 at STA 7021+32.82 and observation of the installation of water storm pipe continued this day.
- At the time of arrival, our representative observed that work was in progress with 6-inch lifts being placed and compacted using a trench and jumping jack compactor.
- Density test results indicate that the compacted materials met the project requirement of 95% of the maximum dry density obtained by a Modified Proctor ASTM D1557.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 05/07/2024
Project No : 2021C002
Client Company : CW Matthews
Arrival Time : 05/07/2024 7:30
Onsite Hours : 9:00

ASEC Report ID : 66437
Name of the Project : Runway 9L End Around Taxiway
Project Location : HJAIA
Weather : sunny
Departure Time : 05/07/2024 16:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.