

Date : 06/27/2023
Project No : 2021C058
Client Company : Pulte Group
Arrival Time : 06/27/2023 17:
Onsite Hours : 02:30

ASEC Report ID : 59990
Name of the Project : Parkside at Mason Mill
Project Location : Decatur, GA
Weather : sunny
Departure Time : 06/27/2023 19:30
ASEC Technician Name : Vidal Shengan

As requested, the site was visited by our AS Engineering and consulting (ASEC) representative for the purpose of providing quality control inspection and testing services.

On this day, our ASEC representative observed the placing of reinforcing steel for Lots #106 thru 112. Our representative found that, in general, reinforcing steel placement was in accordance with the project plans (TYP.WALL SECTION @A5 -01 and A5-02) for size, spacing and quantity.



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.