

Date : 05/20/2023
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/20/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 59415
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : cloudy
Departure Time : 05/20/2023 16:00
ASEC Technician Name : Aminullah Azimi

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
05/20/2023	1	4.5	133.5				Infinity		D6938	Pass
Location : at shoulder of taxi way 6B close to the edge of Lane 5. , Elv/Depth :at finish grade										
Comment : result on hold for proctor										
Tested By : Aminullah Azimi Gauge Serial No. : 85759										
05/20/2023	2	6.1	133.6				Infinity		D6938	Pass
Location : at shoulder taxi way 6B close to lane 4., Elv/Depth :at finish grade										
Comment : result on hold for proctor										
Tested By : Aminullah Azimi Gauge Serial No. : 85759										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 05/20/2023
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/20/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 59415
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : cloudy
Departure Time : 05/20/2023 16:00
ASEC Technician Name : Aminullah Azimi

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
-----------	------------	--------------------------	----------------------	--------------	------------------