

Date : 04/22/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 04/22/2024 8:00
Onsite Hours : 08:00

ASEC Report ID : 66209
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 04/22/2024 16:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift

- Kelly construction continued stripping the topsoil at east side of asphalt shoulder, phase 7B.
- Kelly construction was grading NLVR road located in the east and west asphalt shoulder of Taxiway 20222.
- In case of any questions or concerns with regards to our observations or recommendations stated in this report we will be more than glad to discuss them with you.



Date : 04/22/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 04/22/2024 8:00
Onsite Hours : 08:00

ASEC Report ID : 66209
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 04/22/2024 16:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.