

Date : 05/16/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/16/2024 6:00
Onsite Hours : 07:00

ASEC Report ID : 66539
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 05/16/2024 13:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Observed the placement and testing of concrete for NLVR located on taxiway 2022 phase 7B.

Concrete observed on this date appeared to be placed in compliance with project specifications with regard to temperature, slump, air content, and batch to placement time.



Date : 05/16/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/16/2024 6:00
Onsite Hours : 07:00

ASEC Report ID : 66539
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 05/16/2024 13:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.