

Date : 05/21/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/21/2024 11:00
Onsite Hours : 04:00

ASEC Report ID : 66675
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 05/21/2024 15:00
ASEC Technician Name : Aminullah Azimi

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
05/21/2024	1	4	132.0	GAB 1	135.6	6.8	97.3	95	D6938	Pass
Location : Shoulder of NLVR, N: 9278.6 E: 138525., Elv/Depth :finished grade										
Comment :										
Tested By : Aminullah Azimi Gauge Serial No. : 38069										
05/21/2024	2	3.8	131.4	GAB 1	135.6	6.8	96.9	95	D6938	Pass
Location : Shoulder of NLVR, N: 9279.4 E: 13785.2, Elv/Depth :finished grade										
Comment :										
Tested By : Aminullah Azimi Gauge Serial No. : 38069										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 05/21/2024
Project No : 2022C106
Client Company : CWM
Arrival Time : 05/21/2024 11:00
Onsite Hours : 04:00

ASEC Report ID : 66675
Name of the Project : Taxiway 2022 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 05/21/2024 15:00
ASEC Technician Name : Aminullah Azimi

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
05/02/2023	GAB 1	135.6	6.8	Modified	Graded Aggregate Base