

Date : 04/26/2023
Project No : 2022C113
Client Company : CWM
Arrival Time : 04/26/2023
Onsite Hours :

ASEC Report ID : 59064
Name of the Project : Airfield Sewer Enhancements
Project Location : HJAIA
Weather : cloudy
Departure Time : 04/26/2023
ASEC Technician Name : Russell Hendrix

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative noted above, for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications.

A request was made by CW Matthews for Nuclear compaction testing for the top lift on the Sewer Enhancement project. Placement of lifts for graded aggregate base (GAB) or soil was not observed.

Upon arrival it was determined that the top layer of GAB was contaminated with Soil (see photo). No testing could be conducted. This information was passed on to foreman at R-C and CW Matthews.



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.