

Date : 05/17/2023
Project No : 2022C113
Client Company : CWM
Arrival Time : 05/17/2023 10:00
Onsite Hours : 08:00

ASEC Report ID : 59332
Name of the Project : Airfield Sewer Enhancements
Project Location : HJAIA
Weather : cloudy
Departure Time : 05/17/2023 18:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The placement and compaction of the sewer trench with GAB between MH1 and MH6 and recycled GAB between MH2 and MH3 continued this day.

At the time of arrival, our representative observed that work was in progress with placement continuing to 1 foot below finished grade and compacted using a trench compactor.

Density test results indicate that the compacted materials met the project requirement of 90% (and 95% at finished grade).



Date : 05/17/2023
Project No : 2022C113
Client Company : CWM
Arrival Time : 05/17/2023 10:00
Onsite Hours : 08:00

ASEC Report ID : 59332
Name of the Project : Airfield Sewer Enhancements
Project Location : HJAIA
Weather : cloudy
Departure Time : 05/17/2023 18:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.