

Date : 06/20/2023
Project No : 2022C113
Client Company : CWM
Arrival Time : 06/20/2023 8:30
Onsite Hours : 07:00

ASEC Report ID : 59855
Name of the Project : Airfield Sewer Enhancements
Project Location : HJAIA
Weather : cloudy
Departure Time : 06/20/2023 15:30
ASEC Technician Name : Aminullah Azimi

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
06/20/2023	1	8.1	138.7	Recycled GAB	134.9	8.7	95.1	95	D6938	Pass
Location : 11 feet to west of propose MH#1, Elv/Depth :at finished grade										
Comment :										
Tested By : Aminullah Azimi				Gauge Serial No. : 85759						
06/20/2023	2	10.1	114.0	23347	119.7	13.0	95.2	90	D6938	Pass
Location : at Jock and Pit., Elv/Depth :3 feet below finished grade										
Comment :										
Tested By : Aminullah Azimi				Gauge Serial No. : 85759						

Remark: Test performed in general accordance with signed referenced ASTM Method.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 06/20/2023
Project No : 2022C113
Client Company : CWM
Arrival Time : 06/20/2023 8:30
Onsite Hours : 07:00

ASEC Report ID : 59855
Name of the Project : Airfield Sewer Enhancements
Project Location : HJAIA
Weather : cloudy
Departure Time : 06/20/2023 15:30
ASEC Technician Name : Aminullah Azimi

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
04/04/2023	23346	125.3	11.5	Modified	Reddish Brown Silty Sand with Rock Fragments
04/04/2023	23347	119.7	13.0	Modified	Reddish Brown Silty Sand with Rock Fragments
05/06/2023	GAB 23411	140.2	5.7	Modified	Graded Aggregate Base
05/09/2023	Recycled GAB	134.9	8.7	Modified	Recycled GAB