

Date : 04/28/2023
Project No : 2022C136
Client Company : Century
Arrival Time : 04/28/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 58947
Name of the Project : Logan Pointe
Project Location : Loganville
Weather : cloudy
Departure Time : 04/28/2023 14:30
ASEC Technician Name : Aminullah Azimi

Our As Engineering and Consulting, LLC representative has completed a foundation evaluation for Lots #29, 30, 31, 32, 33, 34. The evaluation was performed by visual inspection, hand probing, dynamic cone penetrometer (DCP) testing. During the evaluation, well compacted fill soils were encountered under lane by residual soils.

These soils were found to be capable of supporting the building structure utilizing an allowable soil bearing pressure of 2500 psf.

As Engineering and Consulting, LLC. appreciates the opportunity to be of service to you on this project. If you have any questions regarding this letter please contact us.

DCP LOCATION:

Lot #29
North/South/Center
etc

DCP-01 Front of the lot**DCP LOCATION:**

Lot #30,
North/South/Center
etc

DCP-02 Rear of the lot

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		7	Tan Silty SAND	1		9	Tan Silty SAND
2		15	Tan Silty SAND	2		15	Tan Silty SAND
3		refusal	Tan Silty SAND	3		refusal	Tan Silty SAND

Date : 04/28/2023
Project No : 2022C136
Client Company : Century
Arrival Time : 04/28/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 58947
Name of the Project : Logan Pointe
Project Location : Loganville
Weather : cloudy
Departure Time : 04/28/2023 14:30
ASEC Technician Name : Aminullah Azimi

DCP LOCATION:

Lot #31,
North/South/Center
etc

DCP-03 Front of the lot

DCP LOCATION:

Lot #32,
North/South/Center
etc

DCP-04 Rear of the lot

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		8	Tan Silty SAND	1		8	Red, Brown Silty SAND
2		16	Tan Silty SAND	2		14	Tan Silty SAND
3		refusal	Tan Silty SAND	3		refusal	Tan Silty SAND

DCP LOCATION:

Lot #33,
North/South/Center
etc

DCP-05 Front of the lot

DCP LOCATION:

Lot #34,
North/South/Center
etc

DCP-06 Rear of the lot

Date : 04/28/2023
Project No : 2022C136
Client Company : Century
Arrival Time : 04/28/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 58947
Name of the Project : Logan Pointe
Project Location : Loganville
Weather : cloudy
Departure Time : 04/28/2023 14:30
ASEC Technician Name : Aminullah Azimi

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		8	Red, Brown Silty SAND	1		8	Red, Brown Silty SAND
2		16	Tan Silty SAND	2		13	Tan Silty SAND
3		refusal	Tan Silty SAND	3		refusal	Tan Silty SAND



Date : 04/28/2023
Project No : 2022C136
Client Company : Century
Arrival Time : 04/28/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 58947
Name of the Project : Logan Pointe
Project Location : Loganville
Weather : cloudy
Departure Time : 04/28/2023 14:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.