

Date : 11/09/2022
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 11/09/2022 06:30
Onsite Hours : 02:30

ASEC Report ID : 55576
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Sunny
Departure Time : 11/09/2022 09:00
ASEC Technician Name : Vidal Dias

AS Engineering and Consulting, LLC (ASEC) visited the site at the client's request to perform footing inspections for Lots #6,8,9,10,12 and 13. During the evaluation, well-compacted fill soils were encountered underlain by residual soils within the planned building pad area.

Lots #8 and 9 refused at two feet using DCP equipment.

One DCP was taken in the remediated area of Lot #10 (outlined in red on the attached image). The area was probed, and one DCP test was performed; well-compacted soils were encountered at the base of each pier.



Vidal Dias
070321636
Project Geologist

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.