

Date : 12/20/2022
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 12/20/2022 07:00
Onsite Hours : 05:00

ASEC Report ID : 55876
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Cloudy and Misty
Departure Time : 12/20/2022 12:00
ASEC Technician Name : Vidal Dias

Our ASEC representative arrived on site to provide visual quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today for the placement of soils for the following areas:

Our ASEC representative observed soils being placed in 8-inch lifts. In the attached photos, the cut area is highlighted in red, the fill area is highlighted in blue, and the density test locations are noted in green. Organic materials were observed in the roadway, and the contractor was advised to remove them. This area is shown in orange on the attached drawing.



Map



Cut Area



Fill Area



Area with organics shown in orange on the map

Vidal Dias
070321636
Project Geologist

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.