

Date : 04/03/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/03/2024 09:00
Onsite Hours : 07:00

ASEC Report ID : 65760
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Cloudy
Departure Time : 04/03/2024 16:00
ASEC Technician Name : Fawad Shagiwal

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services.

The following observations were observed on the site this day.

- Placement and installation of sewer pipe at the sewer pipe trench to MH C1 was in progress.
- Placement and installation of MH C1 was in progress.
- Breaking of rock at the vicinity of Lot #59 was in progress.
- One-layer of 1518 cubic feet soil being placed and compacted at the top of the second layer of rock for the temporary pond between Lots #19 and 20.



Date : 04/03/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/03/2024 09:00
Onsite Hours : 07:00

ASEC Report ID : 65760
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Cloudy
Departure Time : 04/03/2024 16:00
ASEC Technician Name : Fawad Shagiwal



Date : 04/03/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/03/2024 09:00
Onsite Hours : 07:00

ASEC Report ID : 65760
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Cloudy
Departure Time : 04/03/2024 16:00
ASEC Technician Name : Fawad Shagiwal



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.