


Date : 04/22/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/22/2024 02:30
Onsite Hours : 03:30

ASEC Report ID : 66100
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Sunny
Departure Time : 04/22/2024 06:00
ASEC Technician Name : Fawad Shagiwal

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services.

The following observations were observed on the site this day.

- Two layers of 20,096 cubic feet of rock was placed and compacted in temporary pond between Lots #19 and 20 using Excavator (PC390LC) equipment.
- One layer of 10,000 cubic feet of soil and/or rock was placed and compacted at the top of each layer of rock in temporary pond between Lots #19 and 20.



Date : 04/22/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/22/2024 02:30
Onsite Hours : 03:30

ASEC Report ID : 66100
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Sunny
Departure Time : 04/22/2024 06:00
ASEC Technician Name : Fawad Shagiwal



Date : 04/22/2024
Project No : 2022C165
Client Company : Toll Bros. Inc.
Arrival Time : 04/22/2024 02:30
Onsite Hours : 03:30

ASEC Report ID : 66100
Name of the Project : Northfield @ Polo Fields - Phase2
Project Location : Pittman Road, Cumming, GA
Weather : Sunny
Departure Time : 04/22/2024 06:00
ASEC Technician Name : Fawad Shagiwal



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.