

Date : 01/26/2023
Project No : 2022C174
Client Company : CWM
Arrival Time : 01/26/2023
Onsite Hours :

ASEC Report ID : 57455
Name of the Project : CWM Plant on Mulberry Rock Road
Project Location : Dallas, Paulding County
Weather : Cloudy
Departure Time : 01/26/2023
ASEC Technician Name : Russell Hendrix

As requested, our ASEC representative was on site to observe concrete placement for one of the structure slabs placed today. One (1) set of four (4) concrete test specimens were cast. See attached concrete sampling report for results of testing.



Kenneth Mosman

Kenneth Mosman
Project Professional



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.