

Date : 05/15/2023  
Project No : 2022C178  
Client Company : CW Matthews  
Arrival Time : 05/15/2023 8:00  
Onsite Hours : 08:00

ASEC Report ID : 59312  
Name of the Project : Ramp 2 Pavement Replacement  
Project Location : HJAIA  
Weather : rainy  
Departure Time : 05/15/2023 16:00  
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Amin Azimi visited the job site to observe and monitor the contractor's work activities from a quality standpoint to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

- Work was being performed in the Ramp 2 - Phase 4 and sewer enhancements of the project on this day.
- Performed concrete coring and filling and logger reading for Ramp 2 - Phase 4.
- Our representative, along with Depto of ATLQA and ATLNext representative Hazim and CWM rep Brandon observed the process.
- In addition, our ASEC representative observed straight edge testing of Ramp 2 - Phase 4.
- Also observed the installation of pipe between MH#3 and MH#9 and contractor installation of MH#3. GAB compaction was not ready for testing today.



Date : 05/15/2023  
Project No : 2022C178  
Client Company : CW Matthews  
Arrival Time : 05/15/2023 8:00  
Onsite Hours : 08:00

ASEC Report ID : 59312  
Name of the Project : Ramp 2 Pavement Replacement  
Project Location : HJAIA  
Weather : rainy  
Departure Time : 05/15/2023 16:00  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.