

Date : 07/18/2023
Project No : 2022C178
Client Company : CW Matthews
Arrival Time : 07/18/2023 8:30
Onsite Hours : 05:00

ASEC Report ID : 60408
Name of the Project : Ramp 2 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 07/18/2023 13:30
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

- A proof-roll observation was performed on the Ramp 2, phase 10.
- A fully loaded tandem-axle dump truck was used to proof-roll the above-mentioned subgrade with multiple passes across the area.
- Some yielding and deflection were observed during the proof-roll at all areas mentioned above.
- Our representative along with Ashud of ATLQA and the ATLNext representative Hazim observed the proof-roll.
- The under drain was cut and backfilled with #81 stone.



Date : 07/18/2023
Project No : 2022C178
Client Company : CW Matthews
Arrival Time : 07/18/2023 8:30
Onsite Hours : 05:00

ASEC Report ID : 60408
Name of the Project : Ramp 2 Pavement Replacement
Project Location : HJAIA
Weather : sunny
Departure Time : 07/18/2023 13:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.