

Date : 07/15/2022
Project No : 2022C186
Client Company : Excellere
Arrival Time : 07/15/2022 09:30
Onsite Hours : 02:00

ASEC Report ID : 54284
Name of the Project : Midblock Crosswalks
Project Location : Alpharetta
Weather :
Departure Time : 07/15/2022 11:30
ASEC Technician Name : Jamal Geathers

As requested, the site was visited by the AS Engineering and Consulting (ASEC) representative noted above, for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative arrived on site to visually inspect the subgrade for sidewalk placement scheduled for this day. The assessment was done by observing the movement of construction equipment on the subgrade and probing the top of the subgrade. Further a dynamic Cone Penetrometer (DCP) testing was performed with the following results. The sidewalk subgrade was found acceptable for the placement of concrete.

DCP LOCATION: 168 Mayfield Rd Sidewalk

Depth (feet)	Set 2"	N 1.75"	Description
1	5	8	Red silty SAND
2	5	10	Red silty SAND



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.