


Date : 02/14/2023
Project No : 2022C205
Client Company : Pulte
Arrival Time : 02/14/2023 16:00
Onsite Hours : 01:00

ASEC Report ID : 57030
Name of the Project : Enclave at Parkway Village
Project Location : Union City
Weather : Cloudy
Departure Time : 02/14/2023 17:00
ASEC Technician Name : Vidal Shengan

Our ASEC representative visited the site to visually inspect footings for a wall for Lot #87. During the investigation unconsolidated soils were encountered in the top 12 inches of DCP locations 1,2, and 3. The contractor was notified to remove these soils.

Drawings and photos are included below.



Drawing



Lot 87

Kenneth Mosman 

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.