

Date : 01/03/2025
Project No : 2022C205
Client Company : Pulte
Arrival Time : 01/03/2025 09:00
Onsite Hours : 04:00

ASEC Report ID : 75059
Name of the Project : Enclave at Parkway Village
Project Location : Union City
Weather : Sunny
Departure Time : 01/03/2025 13:00
ASEC Technician Name : Micah Aycock

Our representative was on site to perform a foundation inspection for Lot 62. Dynamic Cone Penetrometer (DCP) testing indicated that the foundations were suitable for a soil bearing pressure of 2,000 psf and concrete placement. In-place rebar was found to meet job specifications for size, spacing and quantity.

Please notify us if you have any questions regarding this report.



ASEC Report ID : 75059
Name of the Project : Enclave at Parkway Village
Project Location : Union City
Weather : Sunny
Departure Time : 01/03/2025 13:00
ASEC Technician Name : Micah Aycock

Date : 01/03/2025
Project No : 2022C205
Client Company : Pulte
Arrival Time : 01/03/2025 09:00
Onsite Hours : 04:00



ASEC Report ID : 75059
Name of the Project : Enclave at Parkway Village
Project Location : Union City
Weather : Sunny
Departure Time : 01/03/2025 13:00
ASEC Technician Name : Micah Aycock

Date : 01/03/2025
Project No : 2022C205
Client Company : Pulte
Arrival Time : 01/03/2025 09:00
Onsite Hours : 04:00



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.