


Date : 02/27/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 02/27/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 57339
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : cloudy
Departure Time : 02/27/2023 14:30
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by the AS Engineering and Consulting (ASEC) representative noted above, for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. the following observations were observed on site this day.

The contractor was working on the topsoil and slopes on the west side of lot #404 and East side of lot #428.



Date : 02/27/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 02/27/2023 9:30
Onsite Hours : 05:00

ASEC Report ID : 57339
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : cloudy
Departure Time : 02/27/2023 14:30
ASEC Technician Name : Aminullah Azimi



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.