

Date : 07/14/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 07/14/2023 9:00
Onsite Hours : 04:00

ASEC Report ID : 60297
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : sunny
Departure Time : 07/14/2023 13:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Rock drilling was scheduled for this day, but the drill crew didn't show up.

Observed the placement of soils in the green area located in the Northeast of Lots #431, 432, and 433,



Kenneth Mosman

Kenneth Mosman

Date : 07/14/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 07/14/2023 9:00
Onsite Hours : 04:00

ASEC Report ID : 60297
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : sunny
Departure Time : 07/14/2023 13:00
ASEC Technician Name : Aminullah Azimi

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.