

Date : 09/15/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 09/15/2023 8:30
Onsite Hours : 06:00

ASEC Report ID : 61774
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : sunny
Departure Time : 09/15/2023 14:30
ASEC Technician Name : Aminullah Azimi

The above mentioned AS Engineering and Consulting (ASEC) representative, visited Riverwalk Manor site to perform quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were made on-site:

The following observations were recorded during the shift:

- Our representative observed the drilling of rock and verified the accuracy of the top of rock and termination depths at Road North of Lot#407.
- The resulting volumes were calculated and are presented in a separate report, which is dated in conjunction with the blast day for reference.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 09/15/2023
Project No : 2022C227
Client Company : Artisan
Arrival Time : 09/15/2023 8:30
Onsite Hours : 06:00

ASEC Report ID : 61774
Name of the Project : Riverwalk Manor (CMT) Unit 2, PH 4E
and 4F
Project Location : Dallas
Weather : sunny
Departure Time : 09/15/2023 14:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.