


Date : 02/14/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/14/2023 05:34
Onsite Hours : 10:00

ASEC Report ID : 57006
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Sunny
Departure Time : 02/14/2023 16:30
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities. During the visit, the following observations were made:

1. Ten (10) loads and 230.45 tons of No. 24 stone were delivered and placed in the lower half of the basement.
2. Six (6) loads and 153.88 tons of riprap were delivered and stored near the southeast corner of the basement in area F6.
3. The No. 24 stone was placed according to the job specifications on drawing sheet E720667.

Photo documentation is included below:



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.