

Date : 02/15/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/15/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 57051
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Cloudy and Rain
Departure Time : 02/15/2023 16:30
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities.

During the visit, the following observations were made:

1. The contractor placed 980 square feet of textile fabric in the trench area, located on the south edge of the basement (areas F7 and F8).
2. Crushed concrete and debris were removed from the trench using a CAT 308 mini.
3. Five (5) loads totaling 131.79 tons of riprap were delivered.
4. Three rolls of textile fabric were placed with a two-foot continuous overlap within the lower half of the basement and two feet up the side wall.

Photo documentation is included below:



Date : 02/15/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/15/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 57051
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Cloudy and Rain
Departure Time : 02/15/2023 16:30
ASEC Technician Name : Vidal Dias



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.