

Date : 02/20/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/20/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 57216
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 02/20/2023 16:30
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities.

During the visit, the following observations were made:

1. Three rolls of Terrafabric were placed in the lower half of the basement and secured with stone, which will later be removed once the placement of clayey soils commences.
2. The textile fabric was placed in accordance with the project specifications on drawing E720667.
3. Rip-Rap was placed in the trench located south of the basement in area F7.

Photo documentation is included below:



Date : 02/20/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/20/2023 06:00
Onsite Hours : 10:30

Daily Field Report

ASEC Report ID : 57216
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 02/20/2023 16:30
ASEC Technician Name : Vidal Dias



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.